

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 1

Item ID: D2721-042

Accept



Setup Start



Revision ID:

Stop



Item Name: 206B Step Assembly

Start Date: 8/12/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 8/19/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan:

Date: 8-10-12 Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D2721

Rev C

100

0.00



Large Fab

Large Fab

Memo

0.00

Large Fab

Cut D2721-2 using D2622 extrusion as per Dwg D2721
Deburr and bevel ends for welding8/11/10 17 2 ϕ

110

0.00



Large Fab

Large Fab

Memo

0.00

Large Fab

Weld end cap (One End Only) and lugs as per Dwg D2721 using Jig DT
followed by Jig DT8/11/10 18 2 ϕ

A/R AL Rod Batch:

14514
118735

Grind end cap welds flush

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 2

Item ID: D2721-042
Revision ID:
Item Name: 206B Step Assembly

Accept



Setup Start



Stop



Start Date: 8/12/2011 Start Qty: 2.00
Required Date: 8/19/2011 Req'd Qty: 2.00



Cust Item ID:
Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120 QC Quality Control	QC9- Inspect visual per QSI004- Fusion Welds Memo	0.00 0.00				2	0	8/10/18	
130 QC Quality Control	QC5- Inspect part completeness to step on W/O Memo	0.00 0.00				x2			8/10/18
140 HandFinish Hand Finishing	Chemical Conversion Coat per QSI005 4.1 Memo	0.00 0.00				2X			8/10/18

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 3

Item ID: D2721-042

Accept



Setup Start



Revision ID:

Item Name: 206B Step Assembly

Stop



Start Date: 8/12/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 8/19/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

150

QC3- Inspect Part Finish

0.00



QC

Memo

0.00

Quality Control

2 BL 11-10-20

160

Large Fab

0.00



Large Fab

Memo

0.00

Large Fab

Inspect for foreign object per QSI 024

Weld Remaining end cap as per Dwg D2721

A/R AL Rod Batch: 114514

Grind End Cap Welds Flush

11-10-20

2 /

170

QC9- Inspect visual per QSI004- Fusion Welds

0.00



QC

QC10

Memo

0.00

Quality Control

Sulitz

12 RM

P10 →

Dart Aerospace Ltd

W/O: 72790		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
11/10/21	# 170	change to QC ID inspection	HA	11.10.27	✓	W	S 11/10/24

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 4

Item ID: D2721-042

Accept



Setup Start



Revision ID:

Stop



Item Name: 206B Step Assembly

Start Date: 8/12/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 8/19/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start



QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

180

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

8 11/10/21

x2

RH

190

Chemical Conversion Coat per QSI005 4.1

0.00



HandFinish

Memo

0.00

Hand Finishing

2X M-1 11/10/21

RH

200

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00



Powdercoat

Memo

START TIME:

OVEN TEMPERATURE:

FINISH TIME:

9:00
320 °F
9:30

2X M-1 11/10/24

RH

M117745

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 5

Item ID: D2721-042

Accept



Setup Start



Revision ID:

Stop



Item Name: 206B Step Assembly

Start Date: 8/12/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 8/19/2011 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
210 QC Quality Control	QC3- Inspect Part Finish Memo	0.00 0.00				2		BL 11-10-24	
220 HandFinish Hand Finishing	Wing Walk as per dwg QSI005 4.4 Batch 118988 Memo	0.00				2		BL 11-10-24	
230 QC Quality Control	QC3- Inspect Part Finish Memo	0.00 0.00				2 RM		of JM 11/10/24	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 72790

Friday, August 12, 2011 2:40:03 PM



Page 6

Item ID: D2721-042
Revision ID:
Item Name: 206B Step Assembly

Accept



Setup Start



Stop



Start Date: 8/12/2011 Start Qty: 2.00
Required Date: 8/19/2011 Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
240	Identify as per dwg & Stock Location: _____	0.00							
	Packaging								
	Memo	0.00							
	Packaging								
250	QC21- Final Inspection - Work Order Release	0.00							
	QC								
	Memo	0.00							
	Quality Control								

PDP 72789

11/10/26

28

11/10/26

11-10-26

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Friday, August 12, 2011 2:40:07 PM

[illegible]

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the work.




3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete them.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress to ensure that the objectives are being met.

5. The final step is to evaluate the results of the project. This involves assessing the effectiveness of the plan and identifying any areas for improvement or further action.

Required Qty: 2.00

Comments: IPP Rev:F As Per Ecn 766 06-01-06 JLM IPP Rev:G add wing
walk DD 10.02.24 verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C 		Manufactured	No			100	Each	83.7000	1	2		11.10.18	
Step Extrusion													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				HALL	<u>372131</u>	74				2			
					64409	76							
					68293	68							
				WA		9.7							
					46910	2							
					66970	7.7							
D2734 		Manufactured	No			110	Each	47.0000	1	2		11.10.18	
Step End Plate													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				WA	<u>373194</u>	47				2			
					70701	47							
D3461-1 		Manufactured	No			110	Each	52.0000	1	2		11.10.18	
Mounting Plate													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				WA017		52							
					41600	6				2			
					58756	46							

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, August 12, 2011 2:40:07 PM

Page 2

Work Order ID: 72790

Parent Item: D2721-042

Parent Item Name: 206B Step Assembly

Start Date: 8/12/2011

Required Date: 8/19/2011

Start Qty: 2.00

Required Qty: 2.00

D3461-3

 Manufactured No
 Mounting Plate

110 Each 9.0000 1 2



8.11.10.18

Location Loc Qty Loc Code
 WA017 9

41601 9

2

D3461-5

 Manufactured No
 Mounting Plate

110 Each 25.0000 1 2



8.11.10.18

Location Loc Qty Loc Code
 WA017 25

33862 25

2

D3461-7

 Manufactured No
 Mounting Plate

110 Each 27.0000 1 2



8.11.10.18

Location Loc Qty Loc Code
 WA017 27

33863 27

2

D2734

 Manufactured No
 Step End Plate

160 Each 47.0000 1 2



8.11.10.20

Location Loc Qty Loc Code
 WA 373196 47
 70701 47

2

Friday, August 12, 2011 2:40:07 PM

Shop Packet Print

Page 2

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



RELEASED
05.11.14

DESIGN	PH	DRAWN BY	PH	DART AEROSPACE USA, INC.
CHECKED	PH	APPROVED	PH	PORT HADLOCK, WA
DATE	05.09.19	TITLE	206B STEP ASSEMBLY	REV. C
				SHEET 1 OF 1
				SCALE
				NTS

NOTE: ALL WELDS SHALL
BE 100% VISUALLY
INSPECTED BY A QUALIFIED
INSPECTOR PER DART
QSI 004




D2721-041 LH STEP ASSEMBLY (SHOWN)
D2721-042 RH STEP ASSEMBLY (OPPOSITE)

ROUND CORNER OF EXTRUSION TO
MATCH BEND RADIUS OF END PLATE

D2721-041/-042 STEP ASSEMBLY PARTS LIST

QTY	QTY	PART NUMBER	DESCRIPTION
-041	-042		
X	X	D2721-041	LH STEP ASSEMBLY
		D2721-042	RH STEP ASSEMBLY
1	1	D2622-078	EXTRUSION
2	2	D2734	END PLATE
1	1	D3461-1	PLATE
1	1	D3461-3	PLATE
1	1	D3461-5	PLATE
1	1	D3461-7	PLATE

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 72720



D2721-041/-042 STEP ASSEMBLY

- 1) MAKE FROM EXTRUSION D2622
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
APPLY BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) ALL TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED